

Message Text

PAGE 01 STATE 311909
ORIGIN FBO-05

INFO OCT-01 EA-07 ISO-00 SY-05 A-01 /019 R

DRAFTED BY A/FBO:JKIVIE:CY
APPROVED BY A/FBO:PRSEREY
EA/EX:HWILLIAMS (SUBS)
A/SY:WJHOLDA (DRAFT)
DESIRED DISTRIBUTION
EA/EX:HWILLIAMS, A/SY:WJHOLDA
-----282124Z 013849 /70
R 281929Z DEC 76
FM SECSTATE WASHDC
TO AMEMBASSY WELLINGTON

C O N F I D E N T I A L STATE 311909

E.O. 11652: N/A

TAGS: ABLD, ASEC

SUBJECT: SECURITY MODIFICATIONS - NEW CHANCERY
CONSTRUCTION - PROPERTY NO. 12313-A

REF: (A) WELLINGTON OM 9/28/76 (B) STATE 264169
(C) WELLINGTON OM 8/24/76 (D) WELLINGTON 2792
(E) WELLINGTON OM 6/27/75 (F) SELDEN/IVIE
TELECON OF 12/13/76

1. THE FOLLOWING IS INTENDED TO BE A COMPREHENSIVE REPLY
TO ALL PENDING SECURITY RELATED RECOMMENDATIONS AND
REQUESTS CONCERNING THE NEW CHANCERY BUILDING. THERE
MAY BE SOME DUPLICATION OF APPROVALS, BUT WE HOPE THERE
ARE NOT ANY OMISSIONS.

2. EXTERIOR OF CHANCERY AND SURROUNDING GROUNDS:

CONFIDENTIAL

PAGE 02 STATE 311909

(A) ALL WINDOWS OF THE NEW CHANCERY ARE TO HAVE H-6 TYPE
LAMINATED SAFETY GLASS INSTALLED. THE APPLICATION OF
CLEAR MYLAR WOULD NOT APPRECIABLY INCREASE PROTECTION AND
IS THEREFORE DENIED.

(B) THE INFRA-RED INTRUSION ALARM SYSTEM IS APPROVED FOR
INSTALLATION AT THE CORNERS OF THE BUILDING AS DESCRIBED
IN REF (C). CONDUIT AND MOUNTING POLES SHOULD BE
INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

(C) THE CCTV AT THE FRONT OF THE BUILDING SHOULD BE MOUNTED AT THE INTERSECTIONS OF GRID LINES Q AND 3 AS ORIGINALLY SPECIFIED. THE NECESSARY CONDUIT SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

3. INTERIOR OF CHANCERY, BASEMENT LEVEL:

(A) THE REQUESTED WINDOW BETWEEN ROOMS B-37 AND B-38 IS APPROVED. INCLUDE DESIGN DETAILS IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL. WE QUESTION THE NEED FOR SAFETY GLASS IN THIS WINDOW, AND THEREFORE, ARE APPROVING THE WINDOW WITH ONLY REGULAR GLASS.

(B) THE SIMPLEX LOCK REQUESTED FOR DOOR D-22 IS APPROVED.

(C) DOOR D-2 IS TO BE SECURED WITH A "BRUTE" ELECTRO-MECHANICAL, SURFACE MOUNTED DEADBOLT, CATALOG NUMBER SL-60004. ALL HARDWARE ON THE EXTERIOR SURFACE OF THE DOOR SHOULD BE REMOVED.

(D) THE MARINE GUARD SHOULD HAVE AN INTERCOM AND THE REQUESTED CCTV AVAILABLE AT DOOR D-2 TO FACILITATE IDENTIFICATION OF PERSONS SEEKING ENTRY. THE NECESSARY CONDUIT FOR THE LOCK, INTERCOM AND CCTV SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

CONFIDENTIAL

PAGE 03 STATE 311909

(E) DOORS D-1 AND D-3 SHOULD HAVE MAGNETIC CONTACT SWITCHES INSTALLED. THE REQUEST IS APPROVED. THE NECESSARY CONDUIT SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

(F) DOOR D-3 SHOULD BE INSTALLED WITHOUT EXTERIOR KNOB OR KEYWAY AS SUGGESTED IN REF (E).

(G) THE REQUEST FOR AN ULTRASONIC MOTION DETECTOR IN ROOM B-38 IS DENIED. IT WOULD SERVE NO USEFUL PURPOSE AND THE LIKELIHOOD OF A HIGH FALSE ALARM RATE WOULD DIMINISH THE EFFECTIVENESS OF THIS DEVICE.

4. CHANCERY INTERIOR, FIRST FLOOR LEVEL:

(A) MSG/RECEPTIONIST DESK. IN A MEMORANDUM DATED DECEMBER 15, THE DEPARTMENT (FB0) IS TRANSMITTING AN APPROVED DESIGN DRAWING AND SPECIFICATIONS FOR THIS DESK, AND ADJACENT SECURITY DOORS, WHICH WILL FORM AN EFFECTIVE BARRIER ACROSS THE LOBBY. INTENDED LOCATION OF THE DESK AND DOORS WILL BE APPROXIMATELY ALONG GRID LINE 8, SUBJECT TO NECESSARY ADJUSTMENT BY ON-SITE ANALYSIS. ALL VISITORS ENTERING THE BUILDING WILL BE CONTAINED IN THE

LOBBY UNTIL THEY HAVE BEEN SCREENED AND GIVEN PERMISSION TO ENTER WORKING AREAS. THE SCREENING WILL INCLUDE INSPECTION OF HAND-CARRIED PACKAGES AND A WALK-THROUGH METAL DETECTION DEVICE BEFORE APPROACHING THE MSG/RECEPTIONIST DESK. THE MARINE GUARD WILL CONTROL THE SWITCH TO ELECTRICALLY UNLOCK THE DOOR AND ALLOW CLEARED VISITORS TO PASS THROUGH. THE EMBASSY SHOULD BE RECEIVING THIS MEMORANDUM SHORTLY. INCLUDED IN THE MEMO ARE INSTRUCTIONS FOR PREPARING THE NECESSARY CONTRACTOR'S CHANGE ORDER PROPOSAL.

(B) IT IS AGREED THAT THE SWITCH FOR THE MOTORIZED ROLL-DOWN GRILL SHOULD BE LOCATED AT THE MARINE GUARD DESK.
CONFIDENTIAL

PAGE 04 STATE 311909

NECESSARY CONDUIT SHOULD BE INCLUDED IN THE CHANGE ORDER PROPOSAL.

(C) THE REQUESTED ELECTRICAL CONTROLS FOR DOOR D-6 ARE AGREED WITH AND APPROVED. THIS DOOR SHOULD BE WOOD FRAMED, HAVE DOUBLE SWINGING LEAVES WITH REGULAR PLATE GLASS LIGHTS TO PERMIT VISUAL CONTROL OF THE ELEVATOR BY THE MSG, AND BE MOUNTED ON, OR WITH, AUTOMATIC DOOR CLOSERS. THERE IS NO NEED FOR SAFETY GLASS IN THESE DOOR LEAVES AS THEIR PRIMARY FUNCTION WILL BE INTERMITTENT CONTROL OF VISITORS PREVIOUSLY SCREENED, CLEARED, AND AUTHORIZED ACCESS TO THE PUBLIC AREAS OF THE FIRST FLOOR. THE ELECTRIC LOCKS SHOULD CONSIST OF SOLENOID BOLTS IN THE FRAME ABOVE EACH DOOR LEAF THAT CAN BE ACTIVATED TO LOCK THE DOOR WHEN THE MSG WISHES TO DENY ACCESS TO CORRIDOR 101. NECESSARY CONDUIT, AND DETAILS OF DOOR CONSTRUCTION, SHOULD BE INCLUDED IN THE CHANGE ORDER PROPOSAL.

(D) THE PROPOSED DOORS AT GRID LINE E BETWEEN INTER-SECTIONS 8 AND 9 ARE NOT NECESSARY FOR THE REASONS STATED IN 4(A) ABOVE. THE REQUEST IS DISAPPROVED.

(E) THE FLOOR TO CEILING ARMORED CONSULAR COUNTER IS DISAPPROVED. ALL AUTHORIZED CONSULAR VISITORS WILL HAVE BEEN SCREENED AND CLEARED AND WILL NO LONGER REPRESENT A POTENTIAL THREAT THAT MUST BE COUNTERED BY THESE INCONVENIENT PROTECTIVE BARRIERS.

(F) THE REQUEST TO PLACE ARMOR PLATE IN ALL PARTITION WALLS IS NOT APPROVED. IT MUST BE PRESUMED THAT ANY WEAPON CAPABLE OF PENETRATING A WALL WILL HAVE BEEN DETECTED AND ELIMINATED DURING THE SCREENING PROCESS IN THE LOBBY. THEREFORE, WE SEE NO REASON FOR PROTECTIVE ARMOR WITHIN THE WALLS.

CONFIDENTIAL

PAGE 05 STATE 311909

(G) THE PANIC ALARMS FOR THE USIS RECEPTIONIST AND THE PAO SECRETARY ARE APPROVED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

(H) THE LOBBY MOUNTED CCTV IS APPROVED AS REQUESTED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

(I) WINDOW WALL D-9 THROUGH E-9 AND DOOR D-44 BEING ONE FLOOR ABOVE GROUND LEVEL WILL NOT PROVIDE EASY, NOR UNDETECTABLE, ACCESS FOR CASUAL INTRUDERS. THE SAFETY GLASS INSTALLED WILL PROVIDE PROTECTION AGAINST HANDTHROWN OBJECTS. THEREFORE, THE REQUEST IN REF (E) FOR PROTECTIVE GRILLS IS NOT APPROVED.

(J) THE PRINCIPLE OF GRILLED BARRIERS AND DOORS IN THE STAIRWELLS IS APPROVED. HOWEVER, WE FIND THE USE OF QUARTER INCH BARS ON ONE INCH CENTERS FOR THE GRILLS TO BE EXCESSIVE. THESE BARRIERS CAN BE EQUALLY EFFECTIVE IF FABRICATED FROM HEAVY EXPANDED METAL, OR CHAIN-LINK FENCING, SECURED IN A METAL FRAME AND SOLIDLY FASTENED TO FLOOR, CEILING AND WALLS. THE DOORS MUST NOT BE OF COMBUSTIBLE MATERIAL AND CAN EITHER BE METAL PLATE, OR THE EXPANDED METAL/CHAIN-LINK FENCING USED IN THE SURROUNDING GRILLS. INSTALLATION OF THESE DOORS MUST BE CAREFULLY PLANNED SO THEY WILL IN NO WAY IMPEDE EMERGENCY USE OF THE STAIRS OR CREATE A LIFE PERIL HAZARD IN THE EVENT OF FIRE OR OTHER ALARM. ACCESS THROUGH THE DOORS CAN BE CONTROLLED BY USING WALL MOUNTED ELECTRIC CYPHER LOCKS ON THE OUTSIDE, AND EITHER A PANIC BAR OR HAND OPERATED SWITCH ON THE INSIDE WALL. CARE MUST BE TAKEN TO ENSURE THAT THE INSIDE DOOR CONTROLS CANNOT BE REACHED AND ACTIVATED FROM OUTSIDE THE DOOR OR GRILL. ALL NECESSARY CONDUIT, ELECTRICAL SERVICE REQUIREMENTS, AND DESIGN FEATURES SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

CONFIDENTIAL

PAGE 06 STATE 311909

5. CHANCERY INTERIOR, SECOND FLOOR LEVEL:

(A) THE REQUESTED PANIC ALARM BUTTONS FOR THE AMBASSADOR, DCM AND BOTH SECRETARIES ARE APPROVED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

(B) THE ULTRASONIC ALARMS FOR THE AMBASSADOR AND DCM OFFICES, AND THE ACR PARENT ROOM, ARE CONSIDERED TO BE EXCESSIVE AND ARE NOT APPROVED. THE LIKELIHOOD OF A HIGH FALSE ALARM RATE WOULD TEND TO DIMINISH THE EFFECTIVENESS OF THESE DEVICES.

(C) THE REQUEST FOR A CCTV MONITOR IN THE AMBASSADOR'S OFFICE IS NOT NECESSARY AND IS DENIED. IN THE EVENT OF ANY EMERGENCY OR NOTEWORTHY SITUATIONS, IT IS FELT THAT THE CCTV MONITORING STATION IN THE RSO'S OFFICE WILL BE CONVENIENTLY LOCATED AND READILY ACCESSABLE.

(D) THE REQUEST TO INSTALL ARMOR PLATE IN CERTAIN PARTITION WALLS IS NOT APPROVED FOR THE SAME REASONS GIVEN IN 4(F) ABOVE. CONSCIENTIOUS SCREENING AT THE POINT OF INGRESS TO THE BUILDING WILL OBVIATE THE NEED FOR ARMORING MATERIALS IN ANY INTERIOR WALLS.

(E) WE SIMILARLY DO NOT APPROVE THE REQUEST FOR BULLET RESISTANT MATERIAL IN THE SECOND FLOOR WINDOWS. SEVERAL FACTORS WERE CONSIDERED WITH REGARD TO THIS REQUEST. THE SAFETY GLASS THAT HAS ALREADY BEEN APPROVED FOR INSTALLATION IN THESE WINDOWS WILL PROVIDE A SUFFICIENT PROTECTION AGAINST HANDTHROWN OBJECTS, PARTICULARLY THE TYPE OF PROJECTILES TRADITIONALLY THROWN DURING DEMONSTRATIONS AND RIOTS. WITH CONSIDERATION OF THE DISTANCES INVOLVED IN THE SURROUNDING TERRAIN, THE MOST FEASIBLE SOLUTION TO THIS PROBLEM WOULD BE THE LOCATION OF THE AMBASSADOR'S DESK TO PREVENT DIRECT LINE OF SIGHT, OR FIRE, FROM THE SURROUNDING TERRAIN. DRAPERIES, VENETIAN BLINDS, ETC. CONFIDENTIAL

PAGE 07 STATE 311909

WILL SUFFICIENTLY DECREASE THE POSSIBILITY OF VISUAL ACCESS TO THE AMBASSADOR'S OFFICE AND HENCE PRECLUDE ACCURATE LONG-RANGE SNIPER FIRE.

(F) THE REQUEST TO LOCATE THE RSO AND RELATED EQUIPMENT IN ROOM 215 IS APPROVED. ALL NECESSARY CONDUIT, ELECTRICAL SERVICE REQUIREMENTS, AND SPECIALIZED CONSTRUCTION DETAILS SHOULD BE INCLUDED IN CONTRACTOR'S CHANGE ORDER PROPOSAL.

(G) ALL NECESSARY LOCKING DEVICES FOR THE PREVIOUSLY APPROVED UNCLASSIFIED CONFERENCE ROOM SHOULD BE OBTAINED FROM THE TSO, CANBERRA.

6. CHANCERY INTERIOR, THIRD FLOOR LEVEL:

(A) THE ULTRASONIC ALARMS FOR ROOMS 309 AND 310 ARE DEEMED NECESSARY AND PRUDENT. THE REQUEST IS APPROVED. CONDUIT SHOULD BE INCLUDED IN CHANGE ORDER PROPOSAL.

(B) THE REQUEST FOR A MAGNETIC CONTACT SWITCH ON DOOR D-2 IS APPROVED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

7. THE EMBASSY, FBO PROJECT SUPERVISOR, AND THE CONTRACTOR SHOULD STUDY THE APPROVED REQUESTS, DETERMINE CONDUIT,

ELECTRICAL SERVICE AND CONSTRUCTION REQUIREMENTS. THE
RESULTANT CHANGE ORDER PROPOSAL, TOGETHER WITH DETAILED
DESCRIPTION AND REQUIRED DRAWINGS, SHOULD BE SENT TO
A/FBO FOR REVIEW AND ACTION.
ROBINSON

CONFIDENTIAL

PAGE 01 STATE 011909
ORIGIN FBO-05

INFO OCT-01 EA-07 ISO-00 SY-05 /018 R

66011
DRAFTED BY: A/FBO:JKIVIE:CY
APPROVED BY: A/FBO:PRSEREY
ANA: MAKE C O R R E C T E D C O P Y (MRN 311909 VICE 005493)
-----111013Z 001904 /21/63

R 110128Z JAN 77
FM SECSTATE WASHDC
TO AMCONSUL HONG KONG
INFO AMEMBASSY CANBERRA

C O N F I D E N T I A L STATE 311909

C O R R E C T E D C O P Y/MRN 311909 VICE 005493

HONG KONG FOR RSS AND RTC. CANBERRA FOR TSO

FOLLOWING TEL SENT ACTION WELLINGTON FROM STATE DEC 29:

QUOTE C O N F I D E N T I A L STATE 311909

E.O. 11652: N/A

TAGS: ABLD, ASEC

SUBJECT: SECURITY MODIFICATIONS - NEW CHANCERY
CONSTRUCTION - PROPERTY NO. 12313-A

REF: (A) WELLINGTON OM 9/28/76 (B) STATE 264169
(C) WELLINGTON OM 8/24/76 (D) WELLINGTON 2792
(E) WELLINGTON OM 6/27/75 (F) SELDEN/IVIE
TELECON OF 12/13/76

1. THE FOLLOWING IS INTENDED TO BE A COMPREHENSIVE REPLY
CONFIDENTIAL

PAGE 02 STATE 011909

TO ALL PENDING SECURITY RELATED RECOMMENDATIONS AND
REQUESTS CONCERNING THE NEW CHANCERY BUILDING. THERE
MAY BE SOME DUPLICATION OF APPROVALS, BUT WE HOPE THERE

ARE NOT ANY OMISSIONS.

2. EXTERIOR OF CHANCERY AND SURROUNDING GROUNDS:

(A) ALL WINDOWS OF THE NEW CHANCERY ARE TO HAVE H-6 TYPE LAMINATED SAFETY GLASS INSTALLED. THE APPLICATION OF CLEAR MYLAR WOULD NOT APPRECIABLY INCREASE PROTECTION AND IS THEREFORE DENIED.

(B) THE INFRA-RED INTRUSION ALARM SYSTEM IS APPROVED FOR INSTALLATION AT THE CORNERS OF THE BUILDING AS DESCRIBED IN REF (C). CONDUIT AND MOUNTING POLES SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

(C) THE CCTV AT THE FRONT OF THE BUILDING SHOULD BE MOUNTED AT THE INTERSECTIONS OF GRID LINES Q AND 3 AS ORIGINALLY SPECIFIED. THE NECESSARY CONDUIT SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

3. INTERIOR OF CHANCERY, BASEMENT LEVEL:

(A) THE REQUESTED WINDOW BETWEEN ROOMS B-37 AND B-38 IS APPROVED. INCLUDE DESIGN DETAILS IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL. WE QUESTION THE NEED FOR SAFETY GLASS IN THIS WINDOW, AND THEREFORE, ARE APPROVING THE WINDOW WITH ONLY REGULAR GLASS.

(B) THE SIMPLEX LOCK REQUESTED FOR DOOR D-22 IS APPROVED.

(C) DOOR D-2 IS TO BE SECURED WITH A "BRUTE" ELECTRO-MECHANICAL, SURFACE MOUNTED DEADBOLT, CATALOG NUMBER SL-60004. ALL HARDWARE ON THE EXTERIOR SURFACE OF THE DOOR SHOULD BE REMOVED.
CONFIDENTIAL

PAGE 03 STATE 011909

(D) THE MARINE GUARD SHOULD HAVE AN INTERCOM AND THE REQUESTED CCTV AVAILABLE AT DOOR D-2 TO FACILITATE IDENTIFICATION OF PERSONS SEEKING ENTRY. THE NECESSARY CONDUIT FOR THE LOCK, INTERCOM AND CCTV SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

(E) DOORS D-1 AND D-3 SHOULD HAVE MAGNETIC CONTACT SWITCHES INSTALLED. THE REQUEST IS APPROVED. THE NECESSARY CONDUIT SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

(F) DOOR D-3 SHOULD BE INSTALLED WITHOUT EXTERIOR KNOB OR KEYWAY AS SUGGESTED IN REF (E).

(G) THE REQUEST FOR AN ULTRASONIC MOTION DETECTOR IN ROOM B-38 IS DENIED. IT WOULD SERVE NO USEFUL PURPOSE AND THE LIKELIHOOD OF A HIGH FALSE ALARM RATE WOULD

DIMINISH THE EFFECTIVENESS OF THIS DEVICE.

4. CHANCERY INTERIOR, FIRST FLOOR LEVEL:

(A) MSG/RECEPTIONIST DESK. IN A MEMORANDUM DATED DECEMBER 15, THE DEPARTMENT (FB0) IS TRANSMITTING AN APPROVED DESIGN DRAWING AND SPECIFICATIONS FOR THIS DESK, AND ADJACENT SECURITY DOORS, WHICH WILL FORM AN EFFECTIVE BARRIER ACROSS THE LOBBY. INTENDED LOCATION OF THE DESK AND DOORS WILL BE APPROXIMATELY ALONG GRID LINE 8, SUBJECT TO NECESSARY ADJUSTMENT BY ON-SITE ANALYSIS. ALL VISITORS ENTERING THE BUILDING WILL BE CONTAINED IN THE LOBBY UNTIL THEY HAVE BEEN SCREENED AND GIVEN PERMISSION TO ENTER WORKING AREAS. THE SCREENING WILL INCLUDE INSPECTION OF HAND-CARRIED PACKAGES AND A WALK-THROUGH METAL DETECTION DEVICE BEFORE APPROACHING THE MSG/RECEPTIONIST DESK. THE MARINE GUARD WILL CONTROL THE SWITCH TO ELECTRICALLY UNLOCK THE DOOR AND ALLOW CLEARED CONFIDENTIAL

PAGE 04 STATE 011909

VISITORS TO PASS THROUGH. THE EMBASSY SHOULD BE RECEIVING THIS MEMORANDUM SHORTLY. INCLUDED IN THE MEMO ARE INSTRUCTIONS FOR PREPARING THE NECESSARY CONTRACTOR'S CHANGE ORDER PROPOSAL.

(B) IT IS AGREED THAT THE SWITCH FOR THE MOTORIZED ROLL-DOWN GRILL SHOULD BE LOCATED AT THE MARINE GUARD DESK. NECESSARY CONDUIT SHOULD BE INCLUDED IN THE CHANGE ORDER PROPOSAL.

(C) THE REQUESTED ELECTRICAL CONTROLS FOR DOOR D-6 ARE AGREED WITH AND APPROVED. THIS DOOR SHOULD BE WOOD FRAMED, HAVE DOUBLE SWINGING LEAVES WITH REGULAR PLATE GLASS LIGHTS TO PERMIT VISUAL CONTROL OF THE ELEVATOR BY THE MSG, AND BE MOUNTED ON, OR WITH, AUTOMATIC DOOR CLOSERS. THERE IS NO NEED FOR SAFETY GLASS IN THESE DOOR LEAVES AS THEIR PRIMARY FUNCTION WILL BE INTERMITTENT CONTROL OF VISITORS PREVIOUSLY SCREENED, CLEARED, AND AUTHORIZED ACCESS TO THE PUBLIC AREAS OF THE FIRST FLOOR. THE ELECTRIC LOCKS SHOULD CONSIST OF SOLENOID BOLTS IN THE FRAME ABOVE EACH DOOR LEAF THAT CAN BE ACTIVATED TO LOCK THE DOOR WHEN THE MSG WISHES TO DENY ACCESS TO CORRIDOR 101. NECESSARY CONDUIT, AND DETAILS OF DOOR CONSTRUCTION, SHOULD BE INCLUDED IN THE CHANGE ORDER PROPOSAL.

(D) THE PROPOSED DOORS AT GRID LINE E BETWEEN INTER-SECTIONS 8 AND 9 ARE NOT NECESSARY FOR THE REASONS STATED IN 4(A) ABOVE. THE REQUEST IS DISAPPROVED.

(E) THE FLOOR TO CEILING ARMORED CONSULAR COUNTER IS DISAPPROVED. ALL AUTHORIZED CONSULAR VISITORS WILL HAVE

BEEN SCREENED AND CLEARED AND WILL NO LONGER REPRESENT A POTENTIAL THREAT THAT MUST BE COUNTERED BY THESE INCONVENIENT PROTECTIVE BARRIERS.

CONFIDENTIAL

PAGE 05 STATE 011909

(F) THE REQUEST TO PLACE ARMOR PLATE IN ALL PARTITION WALLS IS NOT APPROVED. IT MUST BE PRESUMED THAT ANY WEAPON CAPABLE OF PENETRATING A WALL WILL HAVE BEEN DETECTED AND ELIMINATED DURING THE SCREENING PROCESS IN THE LOBBY. THEREFORE, WE SEE NO REASON FOR PROTECTIVE ARMOR WITHIN THE WALLS.

(G) THE PANIC ALARMS FOR THE USIS RECEPTIONIST AND THE PAO SECRETARY ARE APPROVED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

(H) THE LOBBY MOUNTED CCTV IS APPROVED AS REQUESTED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

(I) WINDOW WALL D-9 THROUGH E-9 AND DOOR D-44 BEING ONE FLOOR ABOVE GROUND LEVEL WILL NOT PROVIDE EASY, NOR UNDETECTABLE, ACCESS FOR CASUAL INTRUDERS. THE SAFETY GLASS INSTALLED WILL PROVIDE PROTECTION AGAINST HANDTHROWN OBJECTS. THEREFORE, THE REQUEST IN REF (E) FOR PROTECTIVE GRILLS IS NOT APPROVED.

(J) THE PRINCIPLE OF GRILLED BARRIERS AND DOORS IN THE STAIRWELLS IS APPROVED. HOWEVER, WE FIND THE USE OF QUARTER INCH BARS ON ONE INCH CENTERS FOR THE GRILLS TO BE EXCESSIVE. THESE BARRIERS CAN BE EQUALLY EFFECTIVE IF FABRICATED FROM HEAVY EXPANDED METAL, OR CHAIN-LINK FENCING, SECURED IN A METAL FRAME AND SOLIDLY FASTENED TO FLOOR, CEILING AND WALLS. THE DOORS MUST NOT BE OF COMBUSTIBLE MATERIAL AND CAN EITHER BE METAL PLATE, OR THE EXPANDED METAL/CHAIN-LINK FENCING USED IN THE SURROUNDING GRILLS. INSTALLATION OF THESE DOORS MUST BE CAREFULLY PLANNED SO THEY WILL IN NO WAY IMPEDE EMERGENCY USE OF THE STAIRS OR CREATE A LIFE PERIL HAZARD IN THE EVENT OF FIRE OR OTHER ALARM. ACCESS THROUGH THE DOORS CAN BE CONTROLLED BY USING WALL MOUNTED ELECTRIC CYPHER LOCKS ON THE OUTSIDE, AND EITHER A PANIC BAR OR

CONFIDENTIAL

PAGE 06 STATE 011909

HAND OPERATED SWITCH ON THE INSIDE WALL. CARE MUST BE TAKEN TO ENSURE THAT THE INSIDE DOOR CONTROLS CANNOT BE REACHED AND ACTIVATED FROM OUTSIDE THE DOOR OR GRILL. ALL NECESSARY CONDUIT, ELECTRICAL SERVICE REQUIREMENTS, AND DESIGN FEATURES SHOULD BE INCLUDED IN THE CONTRACTOR'S CHANGE ORDER PROPOSAL.

5. CHANCERY INTERIOR, SECOND FLOOR LEVEL:

(A) THE REQUESTED PANIC ALARM BUTTONS FOR THE AMBASSADOR, DCM AND BOTH SECRETARIES ARE APPROVED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

(B) THE ULTRASONIC ALARMS FOR THE AMBASSADOR AND DCM OFFICES, AND THE ACR PARENT ROOM, ARE CONSIDERED TO BE EXCESSIVE AND ARE NOT APPROVED. THE LIKELIHOOD OF A HIGH FALSE ALARM RATE WOULD TEND TO DIMINISH THE EFFECTIVENESS OF THESE DEVICES.

(C) THE REQUEST FOR A CCTV MONITOR IN THE AMBASSADOR'S OFFICE IS NOT NECESSARY AND IS DENIED. IN THE EVENT OF ANY EMERGENCY OR NOTEWORTHY SITUATIONS, IT IS FELT THAT THE CCTV MONITORING STATION IN THE RSO'S OFFICE WILL BE CONVENIENTLY LOCATED AND READILY ACCESSABLE.

(D) THE REQUEST TO INSTALL ARMOR PLATE IN CERTAIN PARTITION WALLS IS NOT APPROVED FOR THE SAME REASONS GIVEN IN 4(F) ABOVE. CONSCIENTIOUS SCREENING AT THE POINT OF INGRESS TO THE BUILDING WILL OBTAIN THE NEED FOR ARMORING MATERIALS IN ANY INTERIOR WALLS.

(E) WE SIMILARLY DO NOT APPROVE THE REQUEST FOR BULLET RESISTANT MATERIAL IN THE SECOND FLOOR WINDOWS. SEVERAL FACTORS WERE CONSIDERED WITH REGARD TO THIS REQUEST. THE SAFETY GLASS THAT HAS ALREADY BEEN APPROVED FOR INSTALLATION IN THESE WINDOWS WILL PROVIDE A SUFFICIENT PROTECTION CONFIDENTIAL

PAGE 07 STATE 011909

AGAINST HANDTHROWN OBJECTS, PARTICULARLY THE TYPE OF PROJECTILES TRADITIONALLY THROWN DURING DEMONSTRATIONS AND RIOTS. WITH CONSIDERATION OF THE DISTANCES INVOLVED IN THE SURROUNDING TERRAIN, THE MOST FEASIBLE SOLUTION TO THIS PROBLEM WOULD BE THE LOCATION OF THE AMBASSADOR'S DESK TO PREVENT DIRECT LINE OF SIGHT, OR FIRE, FROM THE SURROUNDING TERRAIN. DRAPERIES, VENETIAN BLINDS, ETC. WILL SUFFICIENTLY DECREASE THE POSSIBILITY OF VISUAL ACCESS TO THE AMBASSADOR'S OFFICE AND HENCE PRECLUDE ACCURATE LONG-RANGE SNIPER FIRE.

(F) THE REQUEST TO LOCATE THE RSO AND RELATED EQUIPMENT IN ROOM 215 IS APPROVED. ALL NECESSARY CONDUIT, ELECTRICAL SERVICE REQUIREMENTS, AND SPECIALIZED CONSTRUCTION DETAILS SHOULD BE INCLUDED IN CONTRACTOR'S CHANGE ORDER PROPOSAL.

(G) ALL NECESSARY LOCKING DEVICES FOR THE PREVIOUSLY APPROVED UNCLASSIFIED CONFERENCE ROOM SHOULD BE OBTAINED FROM THE TSO, CANBERRA.

6. CHANCERY INTERIOR, THIRD FLOOR LEVEL:

(A) THE ULTRASONIC ALARMS FOR ROOMS 309 AND 310 ARE
DEEMED NECESSARY AND PRUDENT. THE REQUEST IS APPROVED.
CONDUIT SHOULD BE INCLUDED IN CHANGE ORDER PROPOSAL.

(B) THE REQUEST FOR A MAGNETIC CONTACT SWITCH ON DOOR D-2
IS APPROVED. INCLUDE CONDUIT IN CHANGE ORDER PROPOSAL.

7. THE EMBASSY, FBO PROJECT SUPERVISOR, AND THE CONTRACTOR
SHOULD STUDY THE APPROVED REQUESTS, DETERMINE CONDUIT,
ELECTRICAL SERVICE AND CONSTRUCTION REQUIREMENTS. THE
RESULTANT CHANGE ORDER PROPOSAL, TOGETHER WITH DETAILED
DESCRIPTION AND REQUIRED DRAWINGS, SHOULD BE SENT TO
A/FBO FOR REVIEW AND ACTION. ROBINSON UNQUOTE KISSINGER
CONFIDENTIAL

PAGE 08 STATE 011909

CONFIDENTIAL

<< END OF DOCUMENT >>

Message Attributes

Automatic Decaptioning: X
Capture Date: 16 SEP 1999
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 28 DEC 1976
Decaption Date: 01 JAN 1960
Decaption Note:
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Authority: greeneet
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 28 MAY 2004
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1976STATE311909
Document Source: ADS
Document Unique ID: 00
Drafter: A/FBO:JKIVIE:CY
Enclosure: DG ALTERED
Executive Order: N/A
Errors: n/a
Film Number: D760474-0340
From: STATE
Handling Restrictions: n/a
Image Path:
ISecure: 1
Legacy Key: link1976/newtext/t19761293/baaaerco.tel
Line Count: 562
Locator: TEXT ON-LINE, TEXT ON MICROFILM
Office: ORIGIN FBO
Original Classification: CONFIDENTIAL
Original Handling Restrictions: n/a
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 11
Previous Channel Indicators:
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: n/a
Reference: n/a
Review Action: RELEASED, APPROVED
Review Authority: greeneet
Review Comment: n/a
Review Content Flags:
Review Date: 24 MAY 2004
Review Event:
Review Exemptions: n/a
Review History: RELEASED <24 MAY 2004 by BoyleJA>; APPROVED <20 SEP 2004 by greeneet>
Review Markings:

Margaret P. Grafeld
Declassified/Released
US Department of State
EO Systematic Review
04 MAY 2006

Review Media Identifier:
Review Referrals: n/a
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
Secure: OPEN
Status: NATIVE
Subject: SECURITY MODIFICATIONS - NEW CHANCERY
TAGS: ABLD, ASEC
To: WELLINGTON
Type: TE
Markings: Margaret P. Grafeld Declassified/Released US Department of State EO Systematic Review 04 MAY 2006